

CLAY BOPROW EXPRESSION OF INTEREST SUMMARY
DRUMHELLER RESILIENCY AND FLOOD MITIGATION PROGRAM
 March 31, 2022

Source Owner	Contact Individual	Phone Number	Email	Expected Suitability	Comments/ Expected Soil	Provided Borrow Location	Figure #
Knibb Developments Ltd	Jason Knibb	403-312-1951	jason@knibbdevelopments.com	Yes	Clay Till expected to be suitable	SW-28-28-20-W4M	4
Wiarth Dirtwork Ltd	Darcy Wiarth	403-334-7364	d_nwiart@mac.com	Yes	Till expected to be suitable	16-29-31-20-W4M	2
Reg Gallagher	Reg Gallagher	403-820-2670	reg@gallaghertrucking.ca	Yes	Till expected to be suitable	SW-4-31-20-W4M	2
KLS Earthworks Inc.	Mark Walton	403-370-3749	mwalton@kls earthworks.com	Yes	Till expected to be suitable	232098 Range Rd 283, Alberta T1X 0K7	5
Northstar Trucking	Brendan Jensen	780-215-0950	brendan@Northstartrucking.ca	Yes	Till expected to be suitable	41 km North of Drumheller	N/A
Smith Trucking Service (1976) Ltd.	Doug Wutzke	403-633-7880	Doug@Smithtrucking.com	TBD*	No direct testing or observation. North site expected to be till based on client submitted grain size analysis – possibly suitable	South of Drumheller Valley - North location	N/A
McNair Sand and Gravel Inc.	Miles McNair	403-850-5956	Miles@mcnairmsg.ca	TBD*	No information on soil	4-31-13-W4M & 3-31-13-W4M & 2-31-13-W4M	4
D+K Christensen Farms Ltd.	Duane Christensen	403-334-3644	dewakat@aisnet.co	TBD*	No information on soil	S 36-27-19-W4M	4

*TBD - To be decided/ additional information required